

THE PORT AUTHORITY OF NY & NJ

July 11, 2016

United States Environmental Protection Agency
Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866

Attn: NESHAP COORDINATOR


Re: JOHN F. KENNEDY INTERNATIONAL AIRPORT, RUNWAY 31R
GLIDE SLOPE SHACK
OPERATOR PROJECT # 1048.06

Dear Madam/Sir:

Our courtesy for the asbestos abatement work to be done at the above referenced location is attached. Please note our new start date.

If you have any questions, please contact me at 201-595-4881.

Sincerely,



Uday Mehta, Manager
Environmental field Operations
Construction Management Division

Cc: Project File (EPA-2463)
Non-RACM Notification File

UM/fl

241 Erie Street
Room 238
Jersey City, NJ 07310
T: 201 595 4892

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

Operator Project #: 1048.06		Postmark:		Date Received: 06/24/2016		Notification #: EPA-2463	
I. Type of Notification (O=Original R=Revised C=Canceled) O / 1							
II. Facility Information (Identify owner, removal contractor, and other operator)							
Owner Name: THE PORT AUTHORITY OF NY & NJ							
Address: 241 ERIE ST. ROOM 236							
City: JERSEY CITY		State: NJ		Zip: 07310			
Contact: N. CLAYTON, FACILITY SUPERVISOR, ASBESTOS OPS		Telephone: 718-244-4565					
Removal Contractor: NEW YORK ENVIRONMENTAL SERVICES INC.							
Address: 368 RICHARDSON STREET							
City: BROOKLYN		State: NY		Zip: 11222			
Contact: RALPH SEVERINO		Telephone: 718-302-3500					
Other operator: N/A							
Address:							
City:		State:		Zip:			
Contact:		Telephone:					
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) R							
IV. Is Asbestos Present? (Yes/No) YES							
V. Facility Description (include building name, number, floor, and /or room number):							
Building Name: JOHN F. KENNEDY INTERNATIONAL AIRPORT							
Address: JOHN F. KENNEDY INTERNATIONAL AIRPORT							
City: JAMICA		State: NY		County: QUEENS			
Site Location: RUNWAY 31R GLIDE SLOPE SHACK							
Building Size: 300 SQ. FT		# of Floors: 1		Age in Years: 50+			
Present Use: STORAGE				Prior Use: STORAGE			
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: BULK SAMPLING WITH TEM ANALYSIS							
VII. Approximate Amount of Asbestos, Including:							
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed		Non-RACM To Be Removed	RACM to Be Removed	Nonfriable Asbestos Materials Not To Be Removed		Indicate Measurement	
				Cat I	Cat II		
Pipes						Lnft:	0
Surface Area VAT & MASTIC TRANSITE		242 SQ. FT				Sqft:	242
Vol RACM Off Facility Component						Cuft:	0
VIII. Scheduled Dates Asbestos Removal				Start: 07/25/2016		Complete: 11/30/2016	
IX. Scheduled Dates Demo\Renovation				Start:		Complete:	

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

EPA-2463

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used:

REMOVAL USING WET METHODS WITH SURFACE AND ISOLATION BARRIERS

XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos

At the Demolition And Renovation Site:

DUST CONTROL UNING WET METHODS, ISOLATION AND SURFACE BARRIERS,ENGINEERING CONTROLS USING NEGATIVE AIR MACHINES , VACUUMS WITH HEPA FILTERS AND WET REMOVAL, AS PER NEW YORK INDUSTRIAL CODE 56

XII. Waste Transporter #1

Name: ATC

Address: 2 MORICHES MIDDLE ISLAND ROAD

City: SHIRLEY

State: NY

Zip: 11967

Contact: GARY CRETTY

Telephone: 631-924-5050

Waste Transporter #2

Name: N/A

Address:

City:

State:

Zip:

Contact:

Telephone:

XIII. Waste Disposal Site

Name: MINERVA ENTERPRISES

Location: 8955 MINERVA ROAD

City: WAYNESBURG

State: OH

Zip: 44688

Telephone: 330-866-3435

XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below

Name:

Title:

Authority:

Date of Order:

Date Ordered To Begin:

XV. For Emergency Renovations

Date and Hour of Emergency:

Description of Sudden or Unexpected Event:

Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:

XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:

IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS

XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection

(Signature of Owner/Operator)

(Date)

XVIII. I Cerify That the Above Information Is Correct.

(Signature of Owner/Operator)

(Date)